



BRP069B45

MODELS











FTX-K (20/25/35)	1
ATX-K (20/25/35)	
FTXP-K (20/25/35)	
FTXTP-K (25/35)	
ATXP-K (20/25/35)	
ATXTP-K (25/35)	
FTX-K (50/60/71).....	4
FTXP-K (50/60/71)	
FTX-KM (50/60/71).....	7



BRP069B45

1

FTX-K (20/25/35), ATX-K (20/25/35), FTXTTP-K (25/35), FTXP-K (20/25/35), ATXP-K (20/25/35), ATXTTP-K (25/35)










BRP069B45

2

FTX-K (20/25/35), ATX-K (20/25/35), FTXTP-K (25/35), FTXP-K (20/25/35), ATXP-K (20/25/35), ATXTP-K (25/35)






BRP069B45

3

FTX-K (20/25/35), ATX-K (20/25/35), FTXTP-K (25/35), FTXP-K (20/25/35), ATXP-K (20/25/35), ATXTP-K (25/35)












... 3 → 1



BRP069B45

4

FTX-K (50/60/71), FTXP-K (50/60/71)









BRP069B45

5

FTX-K (50/60/71), FTXP-K (50/60/71)





BRP069B45

6

FTX-K (50/60/71), FTXP-K (50/60/71)












... 3 → 1









BRP069B45

7

FTX-KM (50/60/71)



FTX-KM (50/60/71)







BRP069B45

9

FTX-KM (50/60/71)



... 3 → 1